Power down of O350 causes O3900 to panic: pt-2-pt gige connection

Published 08/25/2011

Symptom(s):

Power down of O350 causes O3900 to panic: pt-2-pt gige connection

Fact(s):

IRIX 6.5.26
Origin 350
IRIX 6.5.22
Origin 3900
Patch 7208: IP35 PROM to fix fibre panics in tg_set_flow_ctrl()
Point-to-point Gige connection

SGI Solution:

For systems running Irix 6.5.26 and later, install patch 7208.
For systems running Irix 6.5.22, it's possible to install patch 7208, but 'rulesoverride' needs to set to on from the inst prompt, before installing the patch.

Note: that installing patch 7208 on a 6.5.22 is currently unsupported, and untested by SGI Engineering.

Cause(s):

Bug 920528: fibre panics in tg_set_flow_ctrl() when link partner goes away

Additional Details

Creation Date	02/13/2008 11:32 AM
Last modification	10/01/2015 02:21 AM
Published Date	08/25/2011
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Software • Legacy Software • Operating Systems • IRIX • Peripherals • Networking • Ethernet NIC • Ethernet Switch • Switches and Cables • Storage Infrastructure • SCSI and Fibre Channel Controllers • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution